

PLAYFIELD PROTECTORS

FULL PROTECTION FOR YOUR PINBALL MACHINE

QUICK TIP I „Removing Wet Spots“

1 Wet spots are evaporations of the clear coat.



On new pinball machine the clear coat can evaporate which results in these "wet spots". You can easily get rid of them.

2 Removing evaporations



Please remove slingshots plastics and the rubbers. Then carefully lift the protector.



You can easily "blow" it away with a compressor.



You can alternatively use a hair dryer (without heat!) – but ca takle some time!



The wet spots can come back as long as the clear coat is not fully hardened. If so – please use the same procedure again.

PLAYFIELD PROTECTORS

FULL PROTECTION FOR YOUR PINBALL MACHINE

QUICK TIP I „Entfernen von Flecken“

1 Die Flecken sind Ausdünstungen des Klarlacks.



Bei neuen Flippern bzw. frisch lackierten Spielfeldern kommt es zum Ausgasen vom Klarlack. Dies führt dazu das sich zwischen dem Spielfeld und dem Protektor Feuchtigkeitsflecken entstehen können.

2 Entfernen der Ausdünstungen



Slingshot Plastiken und Gummis entfernen. Dann vorsichtig den Protektor leicht anheben.



Am besten mit Druckluft unter den Protektor blasen.



Alternativ geht auch ein Fön (ohne Hitze) - allerdings dauert dies ein wenig länger. Wenn alle Flecken entfernt sind, Slings wieder zusammenbauen.



Die Flecken werden evtl. noch mal wieder kommen, aber wenn der Klarlack durchgehärtet ist, werden sie nicht wieder auftauchen